

Site HOTO Report — DHK_X1879

Project Tiger · Dhaly Infratech → Alliance Computers Limited · Generated 27-Oct-2026 02:36 BD time

45%

FORM COMPLETION

0/0

CHECKLIST OK

2

OPEN SNAGS

2

TOTAL SNAGS

55

PHOTOS ATTACHED

Incomplete: the following expected fields were left blank in this submission — Site Type, BTS Type, Site Sharing, Site Photo, DG Meter Photo, Fuel Gauge Photo.

SITE & HANDOVER DETAILS

SITE CODE	DHK_X1879	ZONE	Sylhet
HOTO DATE	2026-09-01	DISTRICT	Narsingdi
HANDOVER ORG	Dhaly Infratech	TAKEOVER ORG	Alliance Computers Limited
HANDOVER PERSON	Md. Kabir Hossen	TAKEOVER PERSON	Md. Mahabur Rahman
HANDOVER PHONE	01958313020	TAKEOVER PHONE	01615220637
INSPECTED BY	Md. Mahabur Rahman	SECURITY GUARD	—
ACCESS KEY HANDED OVER	—	SITE TYPE	Not Filled
BTS TYPE	Not Filled		
SHARED WITH OPERATOR	Not Filled	SHARED OPERATOR NAME	—

GENERATOR INFORMATION

DG BRAND	Gentec	GENSET ASSET NO.	N/A
CAPACITY (KVA)	20	TYPE	—
FUEL TANK CAPACITY	1000	PRESENT RH	540.6
FUEL (NO WATER)	206.2 L	FUEL (TOTAL)	236 L
WATER AMOUNT	29.8 L	FUEL AMOUNT (WORD)	—
DG SITE TYPE	Standard	DG LOCKED AFTER FUELING	—
DG PRESENT STATUS	OK	GENSET ON ALARM	OK
BATTERY BRAND	Navana	BATTERY SERIAL	18UE2083
BATTERY AH	100	ENGINE SERIAL	—
ATS BRAND	—	ATS MODE	Auto
RH METER TYPE	—	LAST SERVICE DATE	2026-06-30
KEY TYPE	—	KEY STATUS — BTS	—
KEY STATUS — DG ROOM	—		

ACTIVE DG	—	CONNECTED FUEL TANKS	—
FAULTY/DISCONNECTED DG	—	FAULTY/DISCONNECTED TANKS	—





SNAGS FOUND (2)

SNAG #	SYSTEM	CATEGORY	COMPONENT	STATUS	OBSERVATIONS	ACTION	PHOTO
S-038	DG	Structural/Civil Damage	BTS Room Condition	Faulty	DG Room condition very poor	Open	—
S-039	DG	DG - Mechanical/Fuel	Radiator	Faulty	DG condition poor - need radiator mounting	Open	—

DEFICIENCIES & SAFETY REMARKS

DG MAJOR DEFICIENCIES	—
SAFETY REMARKS	—
GENERAL REMARKS	Digitized from scanned paper HOTO checklist (Narsingdi zone backfill). PDF checklist notes: Site Address: Gohorbazar (handwritten, approx). All connected-generator checklist rows ticked OK except overall remarks flag DG room and DG condition as poor. DG last servicing date noted as 30.06.26. Disconnected generator/spare parts section marked 'All OK'. Handover Status checkboxes (Completed / Not Completed) both appear unmarked/unclear in the scan - could not confirm which was ticked, flagging for human review. Engine serial number field left blank.

SITE PHOTOS

 No Photo Not Filled Site / Nameplate	 No Photo Not Filled DG RH / Meter	 No Photo Not Filled Fuel Gauge			
 Additional	 Additional	 Additional	 Additional	 Additional	 Additional Site Photo

Md. Kabir Hossen

Handed Over By · Dhaly Infratech
01958313020

Date: _____

Md. Mahabur Rahman

Taken Over By · Alliance Computers
Limited
01615220637

Date: _____

BL Concern · Name / Signature

Date: _____

APPENDIX — PHOTO EVIDENCE (55)

Full-size reference photos for DHK_X1879, grouped by type and numbered for cross-reference against the tables above.

ADDITIONAL PHOTOS (55)




Photo 1 — Additional Photos 1



Photo 2 — Additional Photos 2



Photo 3 — Additional Photos 3



Photo 4 — Additional Photos 4



Photo 5 — Additional Photos 5



Photo 6 — Additional Photos 6



Photo 7 — Additional Photos 7




Photo 8 — Additional Photos 8



Photo 9 — Additional Photos 9



Photo 10 — Additional Photos 10



Photo 11 — Additional Photos 11



Photo 12 — Additional Photos 12



Photo 13 — Additional Photos 13




Photo 14 — Additional Photos 14




Photo 15 — Additional Photos 15



Photo 16 — Additional Photos 16






Photo 23 — Additional Photos 23



Photo 24 — Additional Photos 24



Photo 25 — Additional Photos 25



Photo 26 — Additional Photos 26



Photo 27 — Additional Photos 27



Photo 28 — Additional Photos 28



Photo 29 — Additional Photos 29



Photo 30 — Additional Photos 30



Photo 31 — Additional Photos 31



Photo 32 — Additional Photos 32



Photo 33 — Additional Photos 33



Photo 34 — Additional Photos 34



Photo 35 — Additional Photos 35



Photo 36 — Additional Photos 36



Photo 37 — Additional Photos 37




Photo 38 — Additional Photos 38



Photo 39 — Additional Photos 39




Photo 40 — Additional Photos 40



Photo 41 — Additional Photos 41




Photo 42 — Additional Photos 42



Photo 43 — Additional Photos 43



Photo 44 — Additional Photos 44



Photo 45 — Additional Photos 45



Photo 46 — Additional Photos 46



Photo 47 — Additional Photos 47



Photo 48 — Additional Photos 48



Photo 49 — Additional Photos 49



Photo 50 — Additional Photos 50



Photo 51 — Additional Photos 51




Photo 52 — Additional Photos 52



Photo 53 — Additional Photos 53



Photo 54 — Additional Photos 54



Photo 55 — Additional Photos 55