

Site HOTO Report — SYL_X0568

Project Tiger · Dhaly Infratech → Alliance Computers Limited · Generated 27-Oct-2026 02:35 BD time

100%

FORM COMPLETION

15/15

CHECKLIST OK

0

OPEN SNAGS

0

TOTAL SNAGS

37

PHOTOS ATTACHED

SITE & HANDOVER DETAILS

SITE CODE	SYL_X0568	ZONE	Sylhet
HOTO DATE	2026-08-31	DISTRICT	Sunamganj
HANDOVER ORG	Dhaly Infratech Ltd	TAKEOVER ORG	Alliance Computers Ltd
HANDOVER PERSON	Md. Eidris Ali	TAKEOVER PERSON	Md. Ismail Hossain
HANDOVER PHONE	01750537433	TAKEOVER PHONE	01847426858
INSPECTED BY	Ismail Siraji	SECURITY GUARD	No
ACCESS KEY HANDED OVER	Yes	SITE TYPE	GFT
BTS TYPE	Outdoor		
SHARED WITH OPERATOR	Yes	SHARED OPERATOR NAME	Grameen Phone

GENERATOR INFORMATION

DG BRAND	Welland Power	GENSET ASSET NO.	N/A
CAPACITY (KVA)	20	TYPE	Can
FUEL TANK CAPACITY	2000	PRESENT RH	2950.21
FUEL (NO WATER)	282 L	FUEL (TOTAL)	297 L
WATER AMOUNT	15 L	FUEL AMOUNT (WORD)	Two Hundred Eighty Two
DG SITE TYPE	Standard	DG LOCKED AFTER FUELING	Yes
DG PRESENT STATUS	OK	GENSET ON ALARM	OK
BATTERY BRAND	Hamko	BATTERY SERIAL	P033WLDB0108
BATTERY AH	100	ENGINE SERIAL	GV51790V
ATS BRAND	Navana	ATS MODE	Auto
RH METER TYPE	Digital from controller	LAST SERVICE DATE	2026-03-30
KEY TYPE	Local Key	KEY STATUS — BTS	Local
KEY STATUS — DG ROOM	Local		
ACTIVE DG	1	CONNECTED FUEL TANKS	1
FAULTY/DISCONNECTED DG	0	FAULTY/DISCONNECTED TANKS	0

CONNECTED GENERATOR CHECKLIST & READINGS

ITEM	VALUE	ITEM	VALUE
Earth Connection OK	Yes	Load Current (A)	33
Frequency (Hz)	50	Phase	3 Phase
Output	398	Engine Brand	Perkins
Voltage L1-L2	398	Voltage L2-L3	398
Voltage L3-L1	398	Voltage L1-N	230
Voltage L2-N	229	Voltage L3-N	230
Current Line 1	11	Current Line 2	11
Current Line 3	11	N-G	0.040
Controller Status	OK	Black Smoke Status	OK
DG Battery Charger	OK	ATS Physical & Functional Status	OK
DG Automation (VDTC/RVDTC/Rectifier) per BL Standard	OK	Fuel Preserved at Safe & Appropriate Location	OK
Exhaust Fan / Ventilation Sufficient When Running	OK	Sufficient Water in Radiator & Battery	OK
DG Radiator Condition	OK	DG Battery Condition	OK
DG Runs in Both Auto & Manual Mode	OK	GENSET ON Alarm Functioning Properly	OK
Lub Oil Status (Level & Colour)	OK	DG RH Meter Working Properly	OK
No Parts Missing (if missing, note in snags below)	OK		

SNAGS FOUND (0)

No snags logged for this visit.

DEFICIENCIES & SAFETY REMARKS

DG MAJOR DEFICIENCIES	—
SAFETY REMARKS	—
GENERAL REMARKS	PDF checklist notes: IMPORTANT: the 'Site ID' field on this form was left completely BLANK by the writer -- there is no handwritten site code anywhere on the page. The filename/task assignment of SYL_X0568 to this PDF could not be independently verified from the document content itself; confidence downgraded to medium on that basis even though every other field is clearly legible. Cross-check: engine serial 'GV51790' and DG brand 'Welland Power' / Perkins engine closely resemble SYL_X0274's form in this same batch (also GV517904, Welland Power, Perkins, 100A, Auto) -- worth double-checking these aren't two scans of related/nearby sites or a duplicate. Also no Remarks/Snags were written (all checklist items OK/no NOK marks), and neither 'Date of Handover' nor the Completed/Not Completed checkbox was filled in, so handover_status is left null. Given the missing Site ID, a human should re-confirm this PDF truly belongs to SYL_X0568 before using this data to backfill the DB.

SITE PHOTOS




Site /
Nameplate



DG RH / Meter



Fuel Gauge



Additional



Additional



Additional



Additional



Additional



Additional



Additional

Md. Eidris Ali

Handed Over By · Dhaly Infratech Ltd
01750537433

Date: _____

Md. Ismail Hossain

Taken Over By · Alliance Computers Ltd
01847426858

Date: _____

BL Concern · Name / Signature

Date: _____

APPENDIX — PHOTO EVIDENCE (37)

Full-size reference photos for SYL_X0568, grouped by type and numbered for cross-reference against the tables above.

REQUIRED SITE PHOTOS (3)



Photo 1 — Site / Nameplate



Photo 2 — DG RH / Meter



Photo 3 — Fuel Gauge

ADDITIONAL PHOTOS (34)



Photo 4 — Additional Photos 1



Photo 5 — Additional Photos 2



Photo 6 — Additional Photos 3



Photo 7 — Additional Photos 4



Photo 8 — Additional Photos 5



Photo 9 — Additional Photos 6



Photo 10 — Additional Photos 7



Photo 11 — Additional Photos 8




Photo 12 — Additional Photos 9



Photo 13 — Additional Photos 10




Photo 14 — Additional Photos 11



Photo 15 — Additional Photos 12




Photo 16 — Additional Photos 13



Photo 17 — Additional Photos 14



Photo 18 — Additional Photos 15



Photo 19 — Additional Photos 16




Photo 20 — Additional Photos 17



Photo 21 — Additional Photos 18



Photo 22 — Additional Photos 19



Photo 23 — Additional Photos 20



Photo 24 — Additional Photos 21



Photo 25 — Additional Photos 22



Photo 26 — Additional Photos 23



Photo 27 — Additional Photos 24



Photo 28 — Additional Photos 25



Photo 29 — Additional Photos 26



Photo 30 — Additional Photos 27



Photo 31 — Additional Photos 28



Photo 32 — Additional Photos 29



Photo 33 — Additional Photos 30




Photo 34 — Additional Photos 31



Photo 35 — Additional Photos 32



Photo 36 — Additional Photos 33



Photo 37 — Additional Photos 34