

Site HOTO Report — SYL_X0097

Project Tiger · Dhaly Infratech → Alliance Computers Limited · Generated 07-Sep-2026 20:53 BD time

73%

FORM COMPLETION

0/0

CHECKLIST OK

3

OPEN SNAGS

3

TOTAL SNAGS

19

PHOTOS ATTACHED

Incomplete: the following expected fields were left blank in this submission — Site Type, BTS Type, Site Sharing.

SITE & HANDOVER DETAILS

SITE CODE	SYL_X0097	ZONE	Sylhet
HOTO DATE	2026-09-07	DISTRICT	Moulavibazar
HANDOVER ORG	Dhaly Infratech	TAKEOVER ORG	Alliance Computers Limited
HANDOVER PERSON	Abu sayed	TAKEOVER PERSON	Sourav
HANDOVER PHONE	01716332171	TAKEOVER PHONE	01847426870
INSPECTED BY	sourov sarkar	SECURITY GUARD	—
ACCESS KEY HANDED OVER	—	SITE TYPE	Not Filled
BTS TYPE	Not Filled		
SHARED WITH OPERATOR	Not Filled	SHARED OPERATOR NAME	—

GENERATOR INFORMATION


DG BRAND	FG Wilson	GENSET ASSET NO.	—
CAPACITY (KVA)	22	TYPE	—
FUEL TANK CAPACITY	65	PRESENT RH	64.2
FUEL (NO WATER)	63 L	FUEL (TOTAL)	63 L
WATER AMOUNT	— L	FUEL AMOUNT (WORD)	Sixty Three Liters
DG SITE TYPE	Standard	DG LOCKED AFTER FUELING	—
DG PRESENT STATUS	OK	GENSET ON ALARM	OK
BATTERY BRAND	Hamko	BATTERY SERIAL	—
BATTERY AH	—	ENGINE SERIAL	N844L2216M524
ATS BRAND	—	ATS MODE	—
RH METER TYPE	—	LAST SERVICE DATE	—
KEY TYPE	—	KEY STATUS — BTS	—
KEY STATUS — DG ROOM	—		

ACTIVE DG	—	CONNECTED FUEL TANKS	—
FAULTY/DISCONNECTED DG	—	FAULTY/DISCONNECTED TANKS	—

CONNECTED GENERATOR CHECKLIST & READINGS

ITEM	VALUE	ITEM	VALUE
Earth Connection OK	Yes	Load Current (A)	22
Frequency (Hz)	50.2	Phase	3 Phase

SNAGS FOUND (3)

SNAG #	SYSTEM	CATEGORY	COMPONENT	STATUS	OBSERVATIONS	ACTION	PHOTO
S-067	DG	DG - Other	DG room dusty	Faulty	—	Open	
S-068	DG	DG - Other	DG Room Light (□□□□ □□□□ □□□□)	Faulty	—	Open	—
S-069	DG	Structural/Civil Damage	DG room roof tin faulty	Faulty	—	Open	

DEFICIENCIES & SAFETY REMARKS

DG MAJOR DEFICIENCIES	—
SAFETY REMARKS	—
GENERAL REMARKS	—

SITE PHOTOS



Site / Nameplate




DG RH / Meter



Fuel Gauge



Additional



Additional



Additional



Additional



Additional

Abu sayed

Handed Over By · Dhaly Infratech
01716332171

Date: _____

Sourav

Taken Over By · Alliance Computers
Limited
01847426870

Date: _____

BL Concern · Name / Signature

Date: _____

APPENDIX — PHOTO EVIDENCE (19)

Full-size reference photos for SYL_X0097, grouped by type and numbered for cross-reference against the tables above.

REQUIRED SITE PHOTOS (3)



Photo 1 — Site / Nameplate



Photo 2 — DG RH / Meter



Photo 3 — Fuel Gauge

SNAG EVIDENCE PHOTOS (2)



Photo 4 — S-067 — DG room dusty



Photo 5 — S-069 — DG room roof tin faulty

ADDITIONAL PHOTOS (14)



Photo 6 — Site Context 1



Photo 7 — Site Context 2



Photo 8 — Site Context 3



Photo 9 — Site Context 4





Photo 16 — Site Context 11




Photo 17 — Site Context 12



Photo 18 — Site Context 13




Photo 19 — Site Context 14