

Site HOTO Report — SYL_X0043

Project Tiger · Dhaly Infratech → Alliance Computers Limited · Generated 09-Sep-2026 04:45 BD time

91%

FORM COMPLETION

14/15

CHECKLIST OK

1

OPEN SNAGS

1

TOTAL SNAGS

6

PHOTOS ATTACHED

Incomplete: the following expected fields were left blank in this submission — Site Type.

SITE & HANDOVER DETAILS

SITE CODE	SYL_X0043	ZONE	Sylhet
HOTO DATE	2026-08-31	DISTRICT	Sunamganj
HANDOVER ORG	Dhali Infratech Ltd	TAKEOVER ORG	Alliance Computers Limited
HANDOVER PERSON	Md. Eidris Ali	TAKEOVER PERSON	Md. Ismail hossain
HANDOVER PHONE	01750537433	TAKEOVER PHONE	01847426858
INSPECTED BY	Ismail Siraji	SECURITY GUARD	No
ACCESS KEY HANDED OVER	Yes	SITE TYPE	Not Filled
BTS TYPE	Indoor		
SHARED WITH OPERATOR	No	SHARED OPERATOR NAME	N/A

GENERATOR INFORMATION

DG BRAND	Fg wilson	GENSET ASSET NO.	20060052IRD
CAPACITY (KVA)	22	TYPE	Can
FUEL TANK CAPACITY	2000	PRESENT RH	442.8
FUEL (NO WATER)	149 L	FUEL (TOTAL)	186 L
WATER AMOUNT	37 L	FUEL AMOUNT (WORD)	One Hundred Eighty Six Liters
DG SITE TYPE	Standard	DG LOCKED AFTER FUELING	Yes
DG PRESENT STATUS	OK	GENSET ON ALARM	OK
BATTERY BRAND	Hamko	BATTERY SERIAL	P033WECK0207
BATTERY AH	100	ENGINE SERIAL	HP51109U981641P
ATS BRAND	Local	ATS MODE	Auto
RH METER TYPE	Digital from controller	LAST SERVICE DATE	2026-05-24
KEY TYPE	—	KEY STATUS — BTS	LOCAL
KEY STATUS — DG ROOM	LOCAL		

ACTIVE DG	1	CONNECTED FUEL TANKS	1
FAULTY/DISCONNECTED DG	—	FAULTY/DISCONNECTED TANKS	—

CONNECTED GENERATOR CHECKLIST & READINGS

ITEM	VALUE	ITEM	VALUE
Controller Status	OK	Black Smoke Status	OK
DG Battery Charger	OK	ATS Physical & Functional Status	OK
DG Automation (VDTC/RVDTC/Rectifier) per BL Standard	OK	Fuel Preserved at Safe & Appropriate Location	OK
Exhaust Fan / Ventilation Sufficient When Running	OK	Sufficient Water in Radiator & Battery	OK
DG Radiator Condition	OK	DG Battery Condition	OK
DG Runs in Both Auto & Manual Mode	OK	GENSET ON Alarm Functioning Properly	OK
Lub Oil Status (Level & Colour)	NOK	DG RH Meter Working Properly	OK
No Parts Missing (if missing, note in snags below)	OK		


SNAGS FOUND (1)

SNAG #	SYSTEM	CATEGORY	COMPONENT	STATUS	OBSERVATIONS	ACTION	PHOTO
S-001	DG	DG - Other	DG Fan Belt Loose	Faulty	1) Dg fan belt loss 2)charging dynamo properly not setting 3) engine lube oil shortest	Open	

DEFICIENCIES & SAFETY REMARKS

DG MAJOR DEFICIENCIES	—
SAFETY REMARKS	—
GENERAL REMARKS	1) Dg fan belt loss, 2)Charging dynamo properly not setting 3) engine lube oil shortest

SITE PHOTOS

		
Site / Nameplate	DG RH / Meter	Fuel Gauge



Additional



Additional

Md. Eidris Ali

Handed Over By · Dhali Infratech Ltd
01750537433

Date: _____

Md. Ismail hossain

Taken Over By · Alliance Computers
Limited

01847426858

Date: _____

BL Concern · Name / Signature

Date: _____

APPENDIX — PHOTO EVIDENCE (6)

Full-size reference photos for SYL_X0043, grouped by type and numbered for cross-reference against the tables above.

REQUIRED SITE PHOTOS (3)




Photo 1 — Site / Nameplate



Photo 2 — DG RH / Meter



Photo 3 — Fuel Gauge

SNAG EVIDENCE PHOTOS (1)



Photo 4 — S-001 — DG Fan Belt Loose

ADDITIONAL PHOTOS (2)



Photo 5 — Site Context 1




Photo 6 — Site Context 2