

Site HOTO Report — DHK_X2941

Project Tiger · Dhaly Infratech → Alliance Computers Limited · Generated 10-Sep-2026 20:55 BD time

45%

FORM COMPLETION

0/0

CHECKLIST OK

1

OPEN SNAGS

1

TOTAL SNAGS

66

PHOTOS ATTACHED

Incomplete: the following expected fields were left blank in this submission — Site Type, BTS Type, Site Sharing, Site Photo, DG Meter Photo, Fuel Gauge Photo.

SITE & HANDOVER DETAILS

SITE CODE	DHK_X2941	ZONE	Sylhet
HOTO DATE	2026-09-04	DISTRICT	Narsingdi
HANDOVER ORG	—	TAKEOVER ORG	—
HANDOVER PERSON	Md. Kabir Hossen	TAKEOVER PERSON	Sree Bishwajit Kumar
HANDOVER PHONE	—	TAKEOVER PHONE	—
INSPECTED BY	MD KABIR HOSSEN	SECURITY GUARD	—
ACCESS KEY HANDED OVER	—	SITE TYPE	Not Filled
BTS TYPE	Not Filled		
SHARED WITH OPERATOR	Not Filled	SHARED OPERATOR NAME	—

GENERATOR INFORMATION

DG BRAND	Tempest	GENSET ASSET NO.	—
CAPACITY (KVA)	22	TYPE	—
FUEL TANK CAPACITY	67	PRESENT RH	—
FUEL (NO WATER)	— L	FUEL (TOTAL)	48 L
WATER AMOUNT	— L	FUEL AMOUNT (WORD)	—
DG SITE TYPE	—	DG LOCKED AFTER FUELING	—
DG PRESENT STATUS	OK	GENSET ON ALARM	—
BATTERY BRAND	Hamko	BATTERY SERIAL	PO39WJB10279
BATTERY AH	—	ENGINE SERIAL	B17C103786
ATS BRAND	Tempest	ATS MODE	Auto
RH METER TYPE	Manual meter	LAST SERVICE DATE	2026-08-16
KEY TYPE	—	KEY STATUS — BTS	—
KEY STATUS — DG ROOM	—		

ACTIVE DG	1	CONNECTED FUEL TANKS	1
FAULTY/DISCONNECTED DG	—	FAULTY/DISCONNECTED TANKS	—


SNAGS FOUND (1)

SNAG #	SYSTEM	CATEGORY	COMPONENT	STATUS	OBSERVATIONS	ACTION	PHOTO
S-101	General	—	(from HOTO Telegram group photo -- needs review)	Faulty	Auto-tagged as Snag from imported chat photo; please fill in the actual system/category/observation.	Open	

DEFICIENCIES & SAFETY REMARKS

DG MAJOR DEFICIENCIES	DG controller display faulty; MCCB 1pcs output problem; BTS Room Light faulty (from paper handover checklist).
SAFETY REMARKS	—
GENERAL REMARKS	Technical fields backfilled from paper handover checklist photo (DHK_X2941_EXTRA_006.jpg) on 2026-09-09. RH meter reading, phone numbers, and a couple of DG fault counts were illegible/cropped off on the photo -- left blank.

SITE PHOTOS

No Photo Not Filled Site / Nameplate	No Photo Not Filled DG RH / Meter	No Photo Not Filled Fuel Gauge	 Additional	 Additional	 Additional	 Additional	 Additional	 Additional
---	--	---	--	--	---	--	--	--

Md. Kabir Hossen Handed Over By · — — Date: _____	Sree Bishwajit Kumar Taken Over By · — — Date: _____	BL Concern · Name / Signature _____ Date: _____
---	--	--

APPENDIX — PHOTO EVIDENCE (66)

Full-size reference photos for DHK_X2941, grouped by type and numbered for cross-reference against the tables above.

SNAG EVIDENCE PHOTOS (1)



**Photo 1 — S-101 — (from HOTO Telegram group photo
-- needs review)**

ADDITIONAL PHOTOS (65)



Photo 2 — Additional Photos 1



Photo 3 — Additional Photos 2







Photo 10 — Additional Photos 9



Photo 11 — Additional Photos 10



Photo 12 — Additional Photos 11



Photo 13 — Additional Photos 12



Photo 14 — Additional Photos 13



Photo 15 — Additional Photos 14








Photo 22 — Additional Photos 21



Photo 23 — Additional Photos 22



Photo 24 — Additional Photos 23



Photo 25 — Additional Photos 24



Photo 26 — Additional Photos 25



Photo 27 — Additional Photos 26



Photo 28 — Additional Photos 27



Photo 29 — Additional Photos 28



Photo 30 — Additional Photos 29



Photo 31 — Additional Photos 30




Photo 32 — Additional Photos 31




Photo 33 — Additional Photos 32



Photo 34 — Additional Photos 33



Photo 35 — Additional Photos 34



Photo 36 — Additional Photos 35




Photo 37 — Additional Photos 36



Photo 38 — Additional Photos 37



Photo 39 — Additional Photos 38



Photo 40 — Additional Photos 39



Photo 41 — Additional Photos 40



Photo 42 — Additional Photos 41



Photo 43 — Additional Photos 42



Photo 44 — Additional Photos 43



Photo 45 — Additional Photos 44




Photo 46 — Additional Photos 45



Photo 47 — Additional Photos 46



Photo 48 — Additional Photos 47




Photo 49 — Additional Photos 48



Photo 50 — Additional Photos 49



Photo 51 — Additional Photos 50



Photo 52 — Additional Photos 51



Photo 53 — Additional Photos 52



Photo 54 — Additional Photos 53



Photo 55 — Additional Photos 54



Photo 56 — Additional Photos 55



Photo 57 — Additional Photos 56



Photo 58 — Additional Photos 57



Photo 59 — Additional Photos 58



Photo 60 — Additional Photos 59




Photo 61 — Additional Photos 60



Photo 62 — Additional Photos 61



Photo 63 — Additional Photos 62




OPPO A6 Pro
DHK_X2941 - Project Tiger HOTO
Additional Site Photo
09-Sep-2026 14:23 BD time

Photo 64 — Additional Photos 63



OPPO A6 Pro
DHK_X2941 - Project Tiger HOTO
Additional Site Photo
09-Sep-2026 14:23 BD time

Photo 65 — Additional Photos 64



DHK_X2941 - Project Tiger HOTO
Additional Site Photo
09-Sep-2026 14:23 BD time

Photo 66 — Additional Photos 65