

Site HOTO Report — SYL_X0235

Project Tiger · Dhaly Infratech → Alliance Computers Limited · Generated 10-Sep-2026 22:59 BD time

55%

FORM COMPLETION

0/0

CHECKLIST OK

0

OPEN SNAGS

0

TOTAL SNAGS

30

PHOTOS ATTACHED

Incomplete: the following expected fields were left blank in this submission — Site Type, BTS Type, Site Sharing, Site Photo, Fuel Gauge Photo.

SITE & HANDOVER DETAILS

SITE CODE	SYL_X0235	ZONE	Sylhet
HOTO DATE	2026-09-06	DISTRICT	Sylhet
HANDOVER ORG	—	TAKEOVER ORG	—
HANDOVER PERSON	Ali Bahar	TAKEOVER PERSON	Md. Hemayetul Islam
HANDOVER PHONE	—	TAKEOVER PHONE	—
INSPECTED BY	Ali Bahar	SECURITY GUARD	—
ACCESS KEY HANDED OVER	—	SITE TYPE	Not Filled
BTS TYPE	Not Filled		
SHARED WITH OPERATOR	Not Filled	SHARED OPERATOR NAME	—

GENERATOR INFORMATION

DG BRAND	Tempest	GENSET ASSET NO.	—
CAPACITY (KVA)	20	TYPE	—
FUEL TANK CAPACITY	200	PRESENT RH	2530
FUEL (NO WATER)	— L	FUEL (TOTAL)	208 L
WATER AMOUNT	— L	FUEL AMOUNT (WORD)	—
DG SITE TYPE	—	DG LOCKED AFTER FUELING	—
DG PRESENT STATUS	OK	GENSET ON ALARM	—
BATTERY BRAND	Hamko	BATTERY SERIAL	P033WDBE0233
BATTERY AH	100	ENGINE SERIAL	GYV5190U98324013
ATS BRAND	—	ATS MODE	Auto
RH METER TYPE	Manual meter	LAST SERVICE DATE	2026-06-26
KEY TYPE	—	KEY STATUS — BTS	—
KEY STATUS — DG ROOM	—		

ACTIVE DG	—	CONNECTED FUEL TANKS	—
FAULTY/DISCONNECTED DG	—	FAULTY/DISCONNECTED TANKS	—

SNAGS FOUND (0)

No snags logged for this visit.

DEFICIENCIES & SAFETY REMARKS

DG MAJOR DEFICIENCIES	DG Battery water low (from paper handover checklist).
SAFETY REMARKS	—
GENERAL REMARKS	Technical fields backfilled from paper handover checklist photo (SYL_X0235_EXTRA_001.jpg) on 2026-09-09.

SITE PHOTOS

Not Filled

Site / Nameplate




Not Filled

DG RH / Meter

Not Filled

Fuel Gauge



Additional



Additional



Additional



Additional



Additional

Ali Bahar

Handed Over By · —

—

Date: _____

Md. Hemayetul Islam

Taken Over By · —

—

Date: _____

BL Concern · Name / Signature

—

Date: _____

APPENDIX — PHOTO EVIDENCE (30)

Full-size reference photos for SYL_X0235, grouped by type and numbered for cross-reference against the tables above.

REQUIRED SITE PHOTOS (1)



Photo 1 — DG RH / Meter

ADDITIONAL PHOTOS (29)




Photo 2 — Additional Photos 1




Photo 3 — Additional Photos 2



SYL_X0235 · Project Tiger HOTO
Additional Site Photo
09-Sep-2026 14:26 BD time

Photo 4 — Additional Photos 3



SYL_X0235 · Project Tiger HOTO
Additional Site Photo
09-Sep-2026 14:26 BD time

Photo 5 — Additional Photos 4



SYL_X0235 · Project Tiger HOTO
Additional Site Photo
09-Sep-2026 14:26 BD time

Photo 6 — Additional Photos 5



SYL_X0235 · Project Tiger HOTO
Additional Site Photo
09-Sep-2026 14:26 BD time

Photo 7 — Additional Photos 6



SYL_X0235 · Project Tiger HOTO
Additional Site Photo
09-Sep-2026 14:26 BD time

Photo 8 — Additional Photos 7



SYL_X0235 · Project Tiger HOTO
Additional Site Photo
09-Sep-2026 14:26 BD time

Photo 9 — Additional Photos 8



Photo 10 — Additional Photos 9



Photo 11 — Additional Photos 10



Photo 12 — Additional Photos 11



Photo 13 — Additional Photos 12



Photo 14 — Additional Photos 13



Photo 15 — Additional Photos 14



Photo 16 — Additional Photos 15



Photo 17 — Additional Photos 16



Photo 18 — Additional Photos 17



Photo 19 — Additional Photos 18



Photo 20 — Additional Photos 19



Photo 21 — Additional Photos 20



Photo 22 — Additional Photos 21




Photo 23 — Additional Photos 22



Photo 24 — Additional Photos 23



Photo 25 — Additional Photos 24



Photo 26 — Additional Photos 25




Photo 27 — Additional Photos 26



Photo 28 — Additional Photos 27




Photo 29 — Additional Photos 28



Photo 30 — Additional Photos 29