

Site HOTO Report — SYL_X0274

Project Tiger · Dhaly Infratech → Alliance Computers Limited · Generated 07-Sep-2026 22:34 BD time

45%

FORM COMPLETION

0/0

CHECKLIST OK

0

OPEN SNAGS

0

TOTAL SNAGS

0

PHOTOS ATTACHED

Incomplete: the following expected fields were left blank in this submission — Handover Person, Takeover Person, DG Present Status, Site Photo, DG Meter Photo, Fuel Gauge Photo.

SITE & HANDOVER DETAILS

SITE CODE	SYL_X0274	ZONE	Sylhet
HOTO DATE	2026-09-07	DISTRICT	Sunamganj
HANDOVER ORG	Dhaly Infratech	TAKEOVER ORG	Alliance Computers Limited
HANDOVER PERSON	Not Filled	TAKEOVER PERSON	Not Filled
HANDOVER PHONE	—	TAKEOVER PHONE	—
INSPECTED BY	Ismail Siraji	SECURITY GUARD	—
ACCESS KEY HANDED OVER	—	SITE TYPE	GFT
BTS TYPE	Indoor		
SHARED WITH OPERATOR	No	SHARED OPERATOR NAME	N/A

GENERATOR INFORMATION

DG BRAND	—	GENSET ASSET NO.	—
CAPACITY (KVA)	—	TYPE	—
FUEL TANK CAPACITY	—	PRESENT RH	—
FUEL (NO WATER)	— L	FUEL (TOTAL)	— L
WATER AMOUNT	— L	FUEL AMOUNT (WORD)	—
DG SITE TYPE	—	DG LOCKED AFTER FUELING	—
DG PRESENT STATUS	Not Filled	GENSET ON ALARM	—
BATTERY BRAND	—	BATTERY SERIAL	—
BATTERY AH	—	ENGINE SERIAL	—
ATS BRAND	—	ATS MODE	—
RH METER TYPE	—	LAST SERVICE DATE	—
KEY TYPE	—	KEY STATUS — BTS	—
KEY STATUS — DG ROOM	—		

ACTIVE DG	—	CONNECTED FUEL TANKS	—
FAULTY/DISCONNECTED DG	—	FAULTY/DISCONNECTED TANKS	—

CONNECTED GENERATOR CHECKLIST & READINGS

ITEM	VALUE	ITEM	VALUE
------	-------	------	-------

SNAGS FOUND (0)

No snags logged for this visit.

DEFICIENCIES & SAFETY REMARKS

DG MAJOR DEFICIENCIES	—
SAFETY REMARKS	—
GENERAL REMARKS	—

SITE PHOTOS

No Photo

Not Filled

Site / Nameplate

No Photo

Not Filled

DG RH / Meter

No Photo

Not Filled

Fuel Gauge

Handed Over By · Dhaly Infratech

Date: _____

Taken Over By · Alliance Computers Limited

Date: _____

BL Concern · Name / Signature

Date: _____