

Site HOTO Report — DHK_X2656

Project Tiger · Dhaly Infratech → Alliance Computers Limited · Generated 10-Sep-2026 20:55 BD time

18%

FORM COMPLETION

0/0

CHECKLIST OK

3

OPEN SNAGS

3

TOTAL SNAGS

57

PHOTOS ATTACHED

Incomplete: the following expected fields were left blank in this submission — Handover Person, Takeover Person, DG Present Status, Site Type, BTS Type, Site Sharing, Site Photo, DG Meter Photo, Fuel Gauge Photo.

SITE & HANDOVER DETAILS

SITE CODE	DHK_X2656	ZONE	Sylhet
HOTO DATE	2026-09-03	DISTRICT	Kishoreganj
HANDOVER ORG	—	TAKEOVER ORG	—
HANDOVER PERSON	Not Filled	TAKEOVER PERSON	Not Filled
HANDOVER PHONE	—	TAKEOVER PHONE	—
INSPECTED BY	MD KABIR HOSSEN	SECURITY GUARD	—
ACCESS KEY HANDED OVER	—	SITE TYPE	Not Filled
BTS TYPE	Not Filled		
SHARED WITH OPERATOR	Not Filled	SHARED OPERATOR NAME	—

GENERATOR INFORMATION

DG BRAND	—	GENSET ASSET NO.	—
CAPACITY (KVA)	—	TYPE	—
FUEL TANK CAPACITY	—	PRESENT RH	—
FUEL (NO WATER)	— L	FUEL (TOTAL)	— L
WATER AMOUNT	— L	FUEL AMOUNT (WORD)	—
DG SITE TYPE	—	DG LOCKED AFTER FUELING	—
DG PRESENT STATUS	Not Filled	GENSET ON ALARM	—
BATTERY BRAND	—	BATTERY SERIAL	—
BATTERY AH	—	ENGINE SERIAL	—
ATS BRAND	—	ATS MODE	—
RH METER TYPE	—	LAST SERVICE DATE	—
KEY TYPE	—	KEY STATUS — BTS	—
KEY STATUS — DG ROOM	—		

ACTIVE DG	—	CONNECTED FUEL TANKS	—
FAULTY/DISCONNECTED DG	—	FAULTY/DISCONNECTED TANKS	—

SNAGS FOUND (3)

SNAG #	SYSTEM	CATEGORY	COMPONENT	STATUS	OBSERVATIONS	ACTION	PHOTO
S-098	General	—	(from HOTO Telegram group photo -- needs review)	Faulty	Auto-tagged as Snag from imported chat photo; please fill in the actual system/category/observation.	Open	
S-099	General	—	(from HOTO Telegram group photo -- needs review)	Faulty	Auto-tagged as Snag from imported chat photo; please fill in the actual system/category/observation.	Open	
S-100	General	—	(from HOTO Telegram group photo -- needs review)	Faulty	Auto-tagged as Snag from imported chat photo; please fill in the actual system/category/observation.	Open	

DEFICIENCIES & SAFETY REMARKS

DG MAJOR DEFICIENCIES	—
SAFETY REMARKS	—
GENERAL REMARKS	Placeholder visit auto-created from HOTO Telegram group photos on 2026-09-09. Technical fields (DG readings, checklist, snags) still need to be filled in via the app.

SITE PHOTOS

No Photo Not Filled Site / Nameplate	No Photo Not Filled DG RH / Meter	No Photo Not Filled Fuel Gauge	 Additional	 Additional	 Additional	 Additional	 Additional	 Additional
---	--	---	---	---	--	---	---	---

—	—	
Handed Over By · —	Taken Over By · —	BL Concern · Name / Signature
—	—	
Date: _____	Date: _____	Date: _____

APPENDIX — PHOTO EVIDENCE (57)

Full-size reference photos for DHK_X2656, grouped by type and numbered for cross-reference against the tables above.

SNAG EVIDENCE PHOTOS (3)




Photo 1 — S-098 — (from HOTO Telegram group photo -- needs review)



Photo 2 — S-099 — (from HOTO Telegram group photo -- needs review)



Photo 3 — S-100 — (from HOTO Telegram group photo -- needs review)

ADDITIONAL PHOTOS (54)



OPPO A6 Pro
DHK_X2656 · Project Tiger HOTO
Additional Site Photo
09-Sep-2026 14:23 BD time

Photo 4 — Additional Photos 1



OPPO A6 Pro
DHK_X2656 · Project Tiger HOTO
Additional Site Photo
09-Sep-2026 14:23 BD time

Photo 5 — Additional Photos 2



OPPO A6 Pro
DHK_X2656 · Project Tiger HOTO
Additional Site Photo
09-Sep-2026 14:23 BD time

Photo 6 — Additional Photos 3



OPPO A6 Pro
DHK_X2656 · Project Tiger HOTO
Additional Site Photo
09-Sep-2026 14:23 BD time

Photo 7 — Additional Photos 4



OPPO A6 Pro
DHK_X2656 · Project Tiger HOTO
Additional Site Photo
09-Sep-2026 14:23 BD time

Photo 8 — Additional Photos 5



OPPO A6 Pro
DHK_X2656 · Project Tiger HOTO
Additional Site Photo
09-Sep-2026 14:23 BD time

Photo 9 — Additional Photos 6




OPPO A6 Pro
DHK_X2656 · Project Tiger HOTO
Additional Site Photo
09-Sep-2026 14:23 BD time

Photo 10 — Additional Photos 7



OPPO A6 Pro
DHK_X2656 · Project Tiger HOTO
Additional Site Photo
09-Sep-2026 14:23 BD time

Photo 11 — Additional Photos 8



DHK_X2656 · Project Tiger HOTO
Additional Site Photo
09-Sep-2026 14:23 BD time

Photo 12 — Additional Photos 9




DHK_X2656 · Project Tiger HOTO
Additional Site Photo
09-Sep-2026 14:23 BD time

Photo 13 — Additional Photos 10



DHK_X2656 · Project Tiger HOTO
Additional Site Photo
09-Sep-2026 14:23 BD time

Photo 14 — Additional Photos 11



DHK_X2656 · Project Tiger HOTO
Additional Site Photo
09-Sep-2026 14:23 BD time

Photo 15 — Additional Photos 12



Photo 16 — Additional Photos 13



Photo 17 — Additional Photos 14




Photo 18 — Additional Photos 15



Photo 19 — Additional Photos 16



Photo 20 — Additional Photos 17



Photo 21 — Additional Photos 18



Photo 22 — Additional Photos 19



Photo 23 — Additional Photos 20




Photo 24 — Additional Photos 21



Photo 25 — Additional Photos 22



Photo 26 — Additional Photos 23



Photo 27 — Additional Photos 24



Photo 28 — Additional Photos 25



Photo 29 — Additional Photos 26



Photo 30 — Additional Photos 27



Photo 31 — Additional Photos 28



Photo 32 — Additional Photos 29



Photo 33 — Additional Photos 30



Photo 34 — Additional Photos 31



Photo 35 — Additional Photos 32



Photo 36 — Additional Photos 33



Photo 37 — Additional Photos 34



Photo 38 — Additional Photos 35



Photo 39 — Additional Photos 36



Photo 40 — Additional Photos 37



Photo 41 — Additional Photos 38



Photo 42 — Additional Photos 39



Photo 43 — Additional Photos 40



Photo 44 — Additional Photos 41



Photo 45 — Additional Photos 42



Photo 46 — Additional Photos 43



Photo 47 — Additional Photos 44



Photo 48 — Additional Photos 45



Photo 49 — Additional Photos 46



Photo 50 — Additional Photos 47



Photo 51 — Additional Photos 48




Photo 52 — Additional Photos 49



Photo 53 — Additional Photos 50



Photo 54 — Additional Photos 51



Photo 55 — Additional Photos 52



Photo 56 — Additional Photos 53



Photo 57 — Additional Photos 54