

Site HOTO Report — SYL_X0118

Project Tiger · Dhaly Infratech → Alliance Computers Limited · Generated 10-Sep-2026 20:54 BD time

55%

FORM COMPLETION

0/0

CHECKLIST OK

2

OPEN SNAGS

2

TOTAL SNAGS

84

PHOTOS ATTACHED

Incomplete: the following expected fields were left blank in this submission — Site Type, BTS Type, Site Sharing, Site Photo, Fuel Gauge Photo.

SITE & HANDOVER DETAILS

SITE CODE	SYL_X0118	ZONE	Sylhet
HOTO DATE	2026-09-01	DISTRICT	Sylhet
HANDOVER ORG	—	TAKEOVER ORG	—
HANDOVER PERSON	Ali Bahar	TAKEOVER PERSON	Md. Helal Uddin
HANDOVER PHONE	01778700949	TAKEOVER PHONE	01847426880
INSPECTED BY	Ali Bahar	SECURITY GUARD	—
ACCESS KEY HANDED OVER	—	SITE TYPE	Not Filled
BTS TYPE	Not Filled		
SHARED WITH OPERATOR	Not Filled	SHARED OPERATOR NAME	—

GENERATOR INFORMATION

DG BRAND	Tempest	GENSET ASSET NO.	—
CAPACITY (KVA)	20	TYPE	—
FUEL TANK CAPACITY	2550	PRESENT RH	2712.25
FUEL (NO WATER)	— L	FUEL (TOTAL)	151 L
WATER AMOUNT	— L	FUEL AMOUNT (WORD)	—
DG SITE TYPE	—	DG LOCKED AFTER FUELING	—
DG PRESENT STATUS	OK	GENSET ON ALARM	—
BATTERY BRAND	Hamko	BATTERY SERIAL	P033XEBD0622
BATTERY AH	100	ENGINE SERIAL	GV51790U983406B
ATS BRAND	—	ATS MODE	—
RH METER TYPE	—	LAST SERVICE DATE	2026-03-29
KEY TYPE	—	KEY STATUS — BTS	—
KEY STATUS — DG ROOM	—		

ACTIVE DG	—	CONNECTED FUEL TANKS	—
FAULTY/DISCONNECTED DG	—	FAULTY/DISCONNECTED TANKS	—




SNAGS FOUND (2)

SNAG #	SYSTEM	CATEGORY	COMPONENT	STATUS	OBSERVATIONS	ACTION	PHOTO
S-110	General	—	(from HOTO Telegram group photo -- needs review)	Faulty	Auto-tagged as Snag from imported chat photo; please fill in the actual system/category/observation.	Open	
S-111	General	—	(from HOTO Telegram group photo -- needs review)	Faulty	Auto-tagged as Snag from imported chat photo; please fill in the actual system/category/observation.	Open	

DEFICIENCIES & SAFETY REMARKS

DG MAJOR DEFICIENCIES	Battery water and Radiator water short (from paper handover checklist).
SAFETY REMARKS	—
GENERAL REMARKS	Technical fields backfilled from a paper handover checklist photo that was misfiled under SYL_X0200's Extra photos (SYL_X0200_EXTRA_093.jpg) -- the document's own printed Site ID field reads SYL-X0118. Photo has been relocated to this visit. Backfilled 2026-09-09.

SITE PHOTOS

 Not Filled Site / Nameplate	 DG RH / Meter	 Not Filled Fuel Gauge					
 Additional	 Additional	 Additional	 Additional	 Additional	 Additional		

Ali Bahar

Handed Over By · —
01778700949

Date: _____

Md. Helal Uddin

Taken Over By · —
01847426880

Date: _____

BL Concern · Name / Signature

Date: _____

APPENDIX — PHOTO EVIDENCE (84)

Full-size reference photos for SYL_X0118, grouped by type and numbered for cross-reference against the tables above.

REQUIRED SITE PHOTOS (1)




Photo 1 — DG RH / Meter

SNAG EVIDENCE PHOTOS (2)



Photo 2 — S-110 — (from HOTO Telegram group photo
-- needs review)



Photo 3 — S-111 — (from HOTO Telegram group photo
-- needs review)

ADDITIONAL PHOTOS (80)



Photo 4 — Additional Photos 1



Photo 5 — Additional Photos 2



Photo 6 — Additional Photos 3



Photo 7 — Additional Photos 4



Photo 8 — Additional Photos 5



Photo 9 — Additional Photos 6



Photo 10 — Additional Photos 7



Photo 11 — Additional Photos 8



Photo 12 — Additional Photos 9



Photo 13 — Additional Photos 10




Photo 14 — Additional Photos 11



Photo 15 — Additional Photos 12






Photo 22 — Additional Photos 19



Photo 23 — Additional Photos 20



Photo 24 — Additional Photos 21



Photo 25 — Additional Photos 22



Photo 26 — Additional Photos 23





Photo 27 — Additional Photos 24




SYL_X0118 · Project Tiger HOTO
Additional Site Photo
09-Sep-2026 14:25 BD time

Photo 28 — Additional Photos 25




SYL_X0118 · Project Tiger HOTO
Additional Site Photo
09-Sep-2026 14:25 BD time

Photo 29 — Additional Photos 26




SYL_X0118 · Project Tiger HOTO
Additional Site Photo
09-Sep-2026 14:25 BD time

Photo 30 — Additional Photos 27



SYL_X0118 · Project Tiger HOTO
Additional Site Photo
09-Sep-2026 14:25 BD time

Photo 31 — Additional Photos 28



SYL_X0118 · Project Tiger HOTO
Additional Site Photo
09-Sep-2026 14:25 BD time

Photo 32 — Additional Photos 29



SYL_X0118 · Project Tiger HOTO
Additional Site Photo
09-Sep-2026 14:25 BD time

Photo 33 — Additional Photos 30



Photo 34 — Additional Photos 31



Photo 35 — Additional Photos 32



Photo 36 — Additional Photos 33




Photo 37 — Additional Photos 34



Photo 38 — Additional Photos 35






Photo 39 — Additional Photos 36




SYL_X0118 · Project Tiger HOTO
Additional Site Photo
09-Sep-2026 14:25 BD time

Photo 40 — Additional Photos 37




SYL_X0118 · Project Tiger HOTO
Additional Site Photo
09-Sep-2026 14:25 BD time

Photo 41 — Additional Photos 38



SYL_X0118 · Project Tiger HOTO
Additional Site Photo
09-Sep-2026 14:25 BD time

Photo 42 — Additional Photos 39



SYL_X0118 · Project Tiger HOTO
Additional Site Photo
09-Sep-2026 14:25 BD time

Photo 43 — Additional Photos 40



SYL_X0118 · Project Tiger HOTO
Additional Site Photo
09-Sep-2026 14:25 BD time

Photo 44 — Additional Photos 41



SYL_X0118 · Project Tiger HOTO
Additional Site Photo
09-Sep-2026 14:25 BD time

Photo 45 — Additional Photos 42



Photo 46 — Additional Photos 43



Photo 47 — Additional Photos 44



Photo 48 — Additional Photos 45



Photo 49 — Additional Photos 46



Photo 50 — Additional Photos 47



Photo 51 — Additional Photos 48



Photo 52 — Additional Photos 49



Photo 53 — Additional Photos 50



Photo 54 — Additional Photos 51



Photo 55 — Additional Photos 52




Photo 56 — Additional Photos 53




Photo 57 — Additional Photos 54



Photo 58 — Additional Photos 55



Photo 59 — Additional Photos 56



Photo 60 — Additional Photos 57



Photo 61 — Additional Photos 58




Photo 62 — Additional Photos 59



Photo 63 — Additional Photos 60



Photo 64 — Additional Photos 61



Photo 65 — Additional Photos 62



Photo 66 — Additional Photos 63




Photo 67 — Additional Photos 64



Photo 68 — Additional Photos 65




Photo 69 — Additional Photos 66



Photo 70 — Additional Photos 67



Photo 71 — Additional Photos 68



Photo 72 — Additional Photos 69



Photo 73 — Additional Photos 70



Photo 74 — Additional Photos 71




Photo 75 — Additional Photos 72



SYL_X0118 · Project Tiger HOTO
Additional Site Photo
09-Sep-2026 14:25 BD time

Photo 76 — Additional Photos 73



SYL_X0118 · Project Tiger HOTO
Additional Site Photo
09-Sep-2026 14:25 BD time

Photo 77 — Additional Photos 74



SYL_X0118 · Project Tiger HOTO
Additional Site Photo
09-Sep-2026 14:25 BD time

Photo 78 — Additional Photos 75




SYL_X0118 · Project Tiger HOTO
Additional Site Photo
09-Sep-2026 14:25 BD time

Photo 79 — Additional Photos 76



SYL_X0118 · Project Tiger HOTO
Additional Site Photo
09-Sep-2026 14:25 BD time

Photo 80 — Additional Photos 77




SYL_X0200 · Project Tiger HOTO
Additional Site Photo
09-Sep-2026 14:26 BD time

Photo 81 — Additional Photos 78

date-01-09-2026

Checklist for Site Takeover from Operation Tiger Vendor			
Access and Authorization Request			
Site ID: SGL-X0200			
Site Address:			
Site Manager:			
Site ID: 26650			
Site Name:			
Site Type:			
Site Status:			
Site Access:			
Site Security:			
Site Safety:			
Site Health:			
Site Environment:			
Site Infrastructure:			
Site Equipment:			
Site Materials:			
Site Personnel:			
Site Records:			
Site Communications:			
Site Documentation:			
Site Training:			
Site Emergency:			
Site Compliance:			
Site Security:			
Site Safety:			
Site Health:			
Site Environment:			
Site Infrastructure:			
Site Equipment:			
Site Materials:			
Site Personnel:			
Site Records:			
Site Communications:			
Site Documentation:			
Site Training:			
Site Emergency:			
Site Compliance:			
Site Security:			
Site Safety:			
Site Health:			
Site Environment:			
Site Infrastructure:			
Site Equipment:			
Site Materials:			
Site Personnel:			
Site Records:			
Site Communications:			
Site Documentation:			
Site Training:			
Site Emergency:			
Site Compliance:			
Site Security:			
Site Safety:			
Site Health:			
Site Environment:			
Site Infrastructure:			
Site Equipment:			
Site Materials:			
Site Personnel:			
Site Records:			
Site Communications:			
Site Documentation:			
Site Training:			
Site Emergency:			
Site Compliance:			
Site Security:			
Site Safety:			
Site Health:			
Site Environment:			
Site Infrastructure:			
Site Equipment:			
Site Materials:			
Site Personnel:			
Site Records:			
Site Communications:			
Site Documentation:			
Site Training:			
Site Emergency:			
Site Compliance:			
Site Security:			
Site Safety:			
Site Health:			
Site Environment:			
Site Infrastructure:			
Site Equipment:			
Site Materials:			
Site Personnel:			
Site Records:			
Site Communications:			
Site Documentation:			
Site Training:			
Site Emergency:			
Site Compliance:			
Site Security:			
Site Safety:			
Site Health:			
Site Environment:			
Site Infrastructure:			
Site Equipment:			
Site Materials:			
Site Personnel:			
Site Records:			
Site Communications:			
Site Documentation:			
Site Training:			
Site Emergency:			
Site Compliance:			
Site Security:			
Site Safety:			
Site Health:			
Site Environment:			
Site Infrastructure:			
Site Equipment:			
Site Materials:			
Site Personnel:			
Site Records:			
Site Communications:			
Site Documentation:			
Site Training:			
Site Emergency:			
Site Compliance:			
Site Security:			
Site Safety:			
Site Health:			
Site Environment:			
Site Infrastructure:			
Site Equipment:			
Site Materials:			
Site Personnel:			
Site Records:			
Site Communications:			
Site Documentation:			
Site Training:			
Site Emergency:			
Site Compliance:			
Site Security:			
Site Safety:			
Site Health:			
Site Environment:			
Site Infrastructure:			
Site Equipment:			
Site Materials:			
Site Personnel:			
Site Records:			
Site Communications:			
Site Documentation:			
Site Training:			
Site Emergency:			
Site Compliance:			
Site Security:			
Site Safety:			
Site Health:			
Site Environment:			



HANDOVER CHECKLIST DOCUMENT (1)

[illegible]