

Site HOTO Report — SYL_X0247

Project Tiger · Dhaly Infratech → Alliance Computers Limited · Generated 07-Sep-2026 20:23 BD time

100%

FORM COMPLETION

15/15

CHECKLIST OK

2

OPEN SNAGS

2

TOTAL SNAGS

5

PHOTOS ATTACHED

SITE & HANDOVER DETAILS

SITE CODE	SYL_X0247	ZONE	Sylhet
HOTO DATE	2026-09-02	DISTRICT	Sunamganj
HANDOVER ORG	Dhaly Infratech	TAKEOVER ORG	Alliance Computers Limited
HANDOVER PERSON	Md. Edris Ali.	TAKEOVER PERSON	Md. Ismail Hossain.
HANDOVER PHONE	01750537433	TAKEOVER PHONE	01847426858
INSPECTED BY	Ismail Siraji	SECURITY GUARD	No
ACCESS KEY HANDED OVER	Yes	SITE TYPE	GFT
BTS TYPE	Indoor		
SHARED WITH OPERATOR	Yes	SHARED OPERATOR NAME	Grameen Phone

GENERATOR INFORMATION

DG BRAND	Green Power	GENSET ASSET NO.	N/A
CAPACITY (KVA)	22	TYPE	Can
FUEL TANK CAPACITY	2000	PRESENT RH	2350.4
FUEL (NO WATER)	352 L	FUEL (TOTAL)	352 L
WATER AMOUNT	— L	FUEL AMOUNT (WORD)	Three Hundred Fifty Two Liters
DG SITE TYPE	Standard	DG LOCKED AFTER FUELING	Yes
DG PRESENT STATUS	OK	GENSET ON ALARM	OK
BATTERY BRAND	Hamko	BATTERY SERIAL	VIMP8188040007
BATTERY AH	100	ENGINE SERIAL	SK66045U505120
ATS BRAND	Local	ATS MODE	Auto
RH METER TYPE	Digital from controller	LAST SERVICE DATE	2026-03-31
KEY TYPE	Local Key	KEY STATUS — BTS	Local
KEY STATUS — DG ROOM	Local		
ACTIVE DG	1	CONNECTED FUEL TANKS	1

FAULTY/DISCONNECTED DG	—	FAULTY/DISCONNECTED TANKS	—
------------------------	---	---------------------------	---

CONNECTED GENERATOR CHECKLIST & READINGS

ITEM	VALUE	ITEM	VALUE
Earth Connection OK	Yes	Load Current (A)	35
Frequency (Hz)	50.5	Phase	3 Phase
Output	406	Engine Brand	Perkins
Voltage L1-L2	406	Voltage L2-L3	405
Voltage L3-L1	406	Voltage L1-N	233
Voltage L2-N	234	Voltage L3-N	233
Current Line 1	14	Current Line 2	14
Current Line 3	7	N-G	0.045
Controller Status	OK	Black Smoke Status	OK
DG Battery Charger	OK	ATS Physical & Functional Status	OK
DG Automation (VDTC/RVDTC/Rectifier) per BL Standard	OK	Fuel Preserved at Safe & Appropriate Location	OK
Exhaust Fan / Ventilation Sufficient When Running	OK	Sufficient Water in Radiator & Battery	OK
DG Radiator Condition	OK	DG Battery Condition	OK
DG Runs in Both Auto & Manual Mode	OK	GENSET ON Alarm Functioning Properly	OK
Lub Oil Status (Level & Colour)	OK	DG RH Meter Working Properly	OK
No Parts Missing (if missing, note in snags below)	OK		


SNAGS FOUND (2)

SNAG #	SYSTEM	CATEGORY	COMPONENT	STATUS	OBSERVATIONS	ACTION	PHOTO
S-015	DG	DG - Other	DG canopy broken	Faulty	—	Open	
S-016	DG	DG - Controller/Electronics	DG controller install proper way	Faulty	—	Open	

DEFICIENCIES & SAFETY REMARKS

DG MAJOR DEFICIENCIES	DG canopy broken.
SAFETY REMARKS	DG controller install not proper way .
GENERAL REMARKS	—

SITE PHOTOS



Site / Nameplate



DG RH / Meter



Fuel Gauge

Md. Edris Ali.

Handed Over By · Dhaly Infratech
01750537433

Date: _____

Md. Ismail Hossain.

Taken Over By · Alliance Computers
Limited
01847426858

Date: _____

BL Concern · Name / Signature

Date: _____

APPENDIX — PHOTO EVIDENCE (5)

Full-size reference photos for SYL_X0247, grouped by type and numbered for cross-reference against the tables above.

REQUIRED SITE PHOTOS (3)




Photo 1 — Site / Nameplate



Photo 2 — DG RH / Meter



Photo 3 — Fuel Gauge

SNAG EVIDENCE PHOTOS (2)



Photo 4 — S-015 — DG canopy broken



Photo 5 — S-016 — DG controller install proper way