

Site HOTO Report — DHK_X4606

Project Tiger · Dhaly Infratech → Alliance Computers Limited · Generated 07-Sep-2026 20:53 BD time

91%

FORM COMPLETION

15/15

CHECKLIST OK

0

OPEN SNAGS

0

TOTAL SNAGS

17

PHOTOS ATTACHED

Incomplete: the following expected fields were left blank in this submission — Site Sharing.

SITE & HANDOVER DETAILS

SITE CODE	DHK_X4606	ZONE	Sylhet
HOTO DATE	2026-09-03	DISTRICT	Kishoreganj
HANDOVER ORG	Dhaly Infratech	TAKEOVER ORG	Alliance Computers Limited
HANDOVER PERSON	Sree Bishwajeeet Kumar	TAKEOVER PERSON	Md Kobir Hossain
HANDOVER PHONE	018509550252	TAKEOVER PHONE	01958313020
INSPECTED BY	Sojib Hossan	SECURITY GUARD	No
ACCESS KEY HANDED OVER	—	SITE TYPE	GF-RT
BTS TYPE	Outdoor		
SHARED WITH OPERATOR	Not Filled	SHARED OPERATOR NAME	—

GENERATOR INFORMATION

DG BRAND	Welland Power	GENSET ASSET NO.	—
CAPACITY (KVA)	22	TYPE	—
FUEL TANK CAPACITY	2000	PRESENT RH	2089
FUEL (NO WATER)	244 L	FUEL (TOTAL)	270 L
WATER AMOUNT	26 L	FUEL AMOUNT (WORD)	Two Hundred Seventy Liters
DG SITE TYPE	—	DG LOCKED AFTER FUELING	Yes
DG PRESENT STATUS	OK	GENSET ON ALARM	OK
BATTERY BRAND	Hamko	BATTERY SERIAL	PO33WLAG0107
BATTERY AH	—	ENGINE SERIAL	UK255709001977
ATS BRAND	Narada	ATS MODE	Auto
RH METER TYPE	—	LAST SERVICE DATE	—
KEY TYPE	Local Key	KEY STATUS — BTS	—
KEY STATUS — DG ROOM	Local		

ACTIVE DG	1	CONNECTED FUEL TANKS	1
FAULTY/DISCONNECTED DG	1	FAULTY/DISCONNECTED TANKS	1

CONNECTED GENERATOR CHECKLIST & READINGS

ITEM	VALUE	ITEM	VALUE
Phase	3 Phase	Voltage L1-N	232
Voltage L2-N	234	Voltage L3-N	229
Engine Brand	Parking	Controller Status	OK
Black Smoke Status	OK	DG Battery Charger	OK
ATS Physical & Functional Status	OK	DG Automation (VDTC/RVDTC/Rectifier) per BL Standard	OK
Fuel Preserved at Safe & Appropriate Location	OK	Exhaust Fan / Ventilation Sufficient When Running	OK
Sufficient Water in Radiator & Battery	OK	DG Radiator Condition	OK
DG Battery Condition	OK	DG Runs in Both Auto & Manual Mode	OK
GENSET ON Alarm Functioning Properly	OK	Lub Oil Status (Level & Colour)	OK
DG RH Meter Working Properly	OK	No Parts Missing (if missing, note in snags below)	OK

SNAGS FOUND (0)

No snags logged for this visit.

DEFICIENCIES & SAFETY REMARKS

DG MAJOR DEFICIENCIES	1,DG Open Space
SAFETY REMARKS	—
GENERAL REMARKS	—

SITE PHOTOS



Site / Nameplate



DG RH / Meter



Fuel Gauge



Additional



Additional



Additional



Additional



Additional



Additional



Additional



Additional

Sree Bishwajeet Kumar

Handed Over By · Dhaly Infratech
018509550252

Date: _____

Md Kobir Hossain

Taken Over By · Alliance Computers
Limited
01958313020

Date: _____

BL Concern · Name / Signature

Date: _____

APPENDIX — PHOTO EVIDENCE (17)

Full-size reference photos for DHK_X4606, grouped by type and numbered for cross-reference against the tables above.

REQUIRED SITE PHOTOS (3)



Photo 1 — Site / Nameplate



Photo 2 — DG RH / Meter




Photo 3 — Fuel Gauge

ADDITIONAL PHOTOS (14)



Photo 4 — Site Context 1



Photo 5 — Site Context 2



Photo 6 — Site Context 3



Photo 7 — Site Context 4



Photo 8 — Site Context 5



Photo 9 — Site Context 6



Photo 10 — Site Context 7



Photo 11 — Site Context 8



Photo 12 — Site Context 9



Photo 13 — Site Context 10



Photo 14 — Site Context 11



Photo 15 — Site Context 12



Photo 16 — Site Context 13



Photo 17 — Site Context 14