

Site HOTO Report — DHK_X1669

Project Tiger · Dhaly Infratech → Alliance Computers Limited · Generated 09-Sep-2026 19:10 BD time

45%

FORM COMPLETION

0/0

CHECKLIST OK

2

OPEN SNAGS

2

TOTAL SNAGS

62

PHOTOS ATTACHED

Incomplete: the following expected fields were left blank in this submission — Site Type, BTS Type, Site Sharing, Site Photo, DG Meter Photo, Fuel Gauge Photo.

SITE & HANDOVER DETAILS

SITE CODE	DHK_X1669	ZONE	Sylhet
HOTO DATE	2026-09-03	DISTRICT	Kishoreganj
HANDOVER ORG	—	TAKEOVER ORG	—
HANDOVER PERSON	Md. Kabir Hossen	TAKEOVER PERSON	Sirajul Islam
HANDOVER PHONE	01958313020	TAKEOVER PHONE	01899792252
INSPECTED BY	MD KABIR HOSSEN	SECURITY GUARD	—
ACCESS KEY HANDED OVER	—	SITE TYPE	Not Filled
BTS TYPE	Not Filled		
SHARED WITH OPERATOR	Not Filled	SHARED OPERATOR NAME	—

GENERATOR INFORMATION

DG BRAND	METS Energy	GENSET ASSET NO.	—
CAPACITY (KVA)	22	TYPE	—
FUEL TANK CAPACITY	270	PRESENT RH	—
FUEL (NO WATER)	— L	FUEL (TOTAL)	270 L
WATER AMOUNT	— L	FUEL AMOUNT (WORD)	—
DG SITE TYPE	—	DG LOCKED AFTER FUELING	—
DG PRESENT STATUS	OK	GENSET ON ALARM	—
BATTERY BRAND	Spark	BATTERY SERIAL	—
BATTERY AH	—	ENGINE SERIAL	LD6DB-22-06
ATS BRAND	—	ATS MODE	Auto
RH METER TYPE	—	LAST SERVICE DATE	2026-04-20
KEY TYPE	—	KEY STATUS — BTS	—
KEY STATUS — DG ROOM	—		

ACTIVE DG	—	CONNECTED FUEL TANKS	—
FAULTY/DISCONNECTED DG	—	FAULTY/DISCONNECTED TANKS	—


SNAGS FOUND (2)

SNAG #	SYSTEM	CATEGORY	COMPONENT	STATUS	OBSERVATIONS	ACTION	PHOTO
S-079	General	—	(from HOTO Telegram group photo -- needs review)	Faulty	Auto-tagged as Snag from imported chat photo; please fill in the actual system/category/observation.	Open	
S-080	General	—	(from HOTO Telegram group photo -- needs review)	Faulty	Auto-tagged as Snag from imported chat photo; please fill in the actual system/category/observation.	Open	

DEFICIENCIES & SAFETY REMARKS

DG MAJOR DEFICIENCIES	DG open space; DG condition very poor; DG Lub oil short/poor (from paper handover checklist).
SAFETY REMARKS	—
GENERAL REMARKS	Technical fields backfilled from paper handover checklist photo (DHK_X1669_EXTRA_004.jpg) on 2026-09-09. Photo was angled/blurry -- RH meter reading and several OK/NOK checklist rows were illegible, left blank.

SITE PHOTOS

No Photo Not Filled Site / Nameplate	No Photo Not Filled DG RH / Meter	No Photo Not Filled Fuel Gauge	 Additional	 Additional	 Additional	 Additional	 Additional
---	--	---	--	--	---	--	--

Md. Kabir Hossen

Handed Over By · —
01958313020

Date: _____

Sirajul Islam

Taken Over By · —
01899792252

Date: _____

BL Concern · Name / Signature

Date: _____

APPENDIX — PHOTO EVIDENCE (62)

Full-size reference photos for DHK_X1669, grouped by type and numbered for cross-reference against the tables above.

SNAG EVIDENCE PHOTOS (2)



Photo 1 — S-079 — (from HOTO Telegram group photo
-- needs review)



Photo 2 — S-080 — (from HOTO Telegram group photo
-- needs review)

ADDITIONAL PHOTOS (60)




Photo 3 — Additional Photos 1



Photo 4 — Additional Photos 2




Photo 5 — Additional Photos 3




Photo 6 — Additional Photos 4




Photo 7 — Additional Photos 5



Photo 8 — Additional Photos 6



Photo 9 — Additional Photos 7




Photo 10 — Additional Photos 8



Photo 11 — Additional Photos 9



Photo 12 — Additional Photos 10



Photo 13 — Additional Photos 11



Photo 14 — Additional Photos 12



Photo 15 — Additional Photos 13



Photo 16 — Additional Photos 14



Photo 17 — Additional Photos 15




Photo 18 — Additional Photos 16



Photo 19 — Additional Photos 17



Photo 20 — Additional Photos 18



Photo 21 — Additional Photos 19



Photo 22 — Additional Photos 20



Photo 23 — Additional Photos 21



Photo 24 — Additional Photos 22



Photo 25 — Additional Photos 23



Photo 26 — Additional Photos 24



Photo 27 — Additional Photos 25




Photo 28 — Additional Photos 26



Photo 29 — Additional Photos 27



Photo 30 — Additional Photos 28



Photo 31 — Additional Photos 29



Photo 32 — Additional Photos 30



Photo 33 — Additional Photos 31



Photo 34 — Additional Photos 32



Photo 35 — Additional Photos 33



Photo 36 — Additional Photos 34



Photo 37 — Additional Photos 35



Photo 38 — Additional Photos 36




Photo 39 — Additional Photos 37



Photo 40 — Additional Photos 38



Photo 41 — Additional Photos 39



Photo 42 — Additional Photos 40



Photo 43 — Additional Photos 41



Photo 44 — Additional Photos 42



Photo 45 — Additional Photos 43



Photo 46 — Additional Photos 44



Photo 47 — Additional Photos 45



Photo 48 — Additional Photos 46



Photo 49 — Additional Photos 47



Photo 50 — Additional Photos 48



Photo 51 — Additional Photos 49



Photo 52 — Additional Photos 50



Photo 53 — Additional Photos 51



Photo 54 — Additional Photos 52



Photo 55 — Additional Photos 53



Photo 56 — Additional Photos 54



Photo 57 — Additional Photos 55



Photo 58 — Additional Photos 56



Photo 59 — Additional Photos 57



Photo 60 — Additional Photos 58



Photo 61 — Additional Photos 59



Photo 62 — Additional Photos 60