

Site HOTO Report — DHK_X2063

Project Tiger · Dhaly Infratech → Alliance Computers Limited · Generated 10-Sep-2026 20:54 BD time

27%

FORM COMPLETION

0/0

CHECKLIST OK

3

OPEN SNAGS

3

TOTAL SNAGS

60

PHOTOS ATTACHED

Incomplete: the following expected fields were left blank in this submission — Handover Person, Takeover Person, Site Type, BTS Type, Site Sharing, Site Photo, DG Meter Photo, Fuel Gauge Photo.

SITE & HANDOVER DETAILS

SITE CODE	DHK_X2063	ZONE	Sylhet
HOTO DATE	2026-09-06	DISTRICT	Narsingdi
HANDOVER ORG	—	TAKEOVER ORG	—
HANDOVER PERSON	Not Filled	TAKEOVER PERSON	Not Filled
HANDOVER PHONE	—	TAKEOVER PHONE	—
INSPECTED BY	MD KABIR HOSSEN	SECURITY GUARD	—
ACCESS KEY HANDED OVER	—	SITE TYPE	Not Filled
BTS TYPE	Not Filled		
SHARED WITH OPERATOR	Not Filled	SHARED OPERATOR NAME	—

GENERATOR INFORMATION

DG BRAND	—	GENSET ASSET NO.	—
CAPACITY (KVA)	30	TYPE	—
FUEL TANK CAPACITY	2000	PRESENT RH	5372
FUEL (NO WATER)	— L	FUEL (TOTAL)	278 L
WATER AMOUNT	— L	FUEL AMOUNT (WORD)	—
DG SITE TYPE	—	DG LOCKED AFTER FUELING	—
DG PRESENT STATUS	OK	GENSET ON ALARM	—
BATTERY BRAND	Spark	BATTERY SERIAL	—
BATTERY AH	100	ENGINE SERIAL	FGWPEP37JJSA03480
ATS BRAND	—	ATS MODE	Auto
RH METER TYPE	Manual meter	LAST SERVICE DATE	2026-03-28
KEY TYPE	—	KEY STATUS — BTS	—
KEY STATUS — DG ROOM	—		

ACTIVE DG	—	CONNECTED FUEL TANKS	—
FAULTY/DISCONNECTED DG	—	FAULTY/DISCONNECTED TANKS	—



SNAGS FOUND (3)

SNAG #	SYSTEM	CATEGORY	COMPONENT	STATUS	OBSERVATIONS	ACTION	PHOTO
S-086	General	—	(from HOTO Telegram group photo -- needs review)	Faulty	Auto-tagged as Snag from imported chat photo; please fill in the actual system/category/observation.	Open	
S-087	General	—	(from HOTO Telegram group photo -- needs review)	Faulty	Auto-tagged as Snag from imported chat photo; please fill in the actual system/category/observation.	Open	
S-088	General	—	(from HOTO Telegram group photo -- needs review)	Faulty	Auto-tagged as Snag from imported chat photo; please fill in the actual system/category/observation.	Open	

DEFICIENCIES & SAFETY REMARKS

DG MAJOR DEFICIENCIES	—
SAFETY REMARKS	—
GENERAL REMARKS	Technical fields backfilled from paper handover checklist photo (DHK_X2063_EXTRA_001.jpg) on 2026-09-09. Generator brand, battery serial, and the Remarks/Snag Summary text were largely obscured by photo glare/folds -- left blank/incomplete, worth a re-check against the physical form.

SITE PHOTOS

Not Filled No Photo Site / Nameplate	Not Filled No Photo DG RH / Meter	Not Filled No Photo Fuel Gauge	 Additional	 Additional	 Additional	 Additional	 Additional	 Additional
--	---	--	--	--	--	--	--	--

—	—	
Handed Over By · —	Taken Over By · —	BL Concern · Name / Signature
—	—	
Date: _____	Date: _____	Date: _____

APPENDIX — PHOTO EVIDENCE (60)

Full-size reference photos for DHK_X2063, grouped by type and numbered for cross-reference against the tables above.

SNAG EVIDENCE PHOTOS (3)



Photo 1 — S-086 — (from HOTO Telegram group photo -- needs review)



Photo 2 — S-087 — (from HOTO Telegram group photo -- needs review)



Photo 3 — S-088 — (from HOTO Telegram group photo -- needs review)

ADDITIONAL PHOTOS (57)




Photo 4 — Additional Photos 1




Photo 5 — Additional Photos 2




Photo 6 — Additional Photos 3



Photo 7 — Additional Photos 4



Photo 8 — Additional Photos 5



Photo 9 — Additional Photos 6



Photo 10 — Additional Photos 7




Photo 11 — Additional Photos 8



Photo 12 — Additional Photos 9



Photo 13 — Additional Photos 10



Photo 14 — Additional Photos 11



Photo 15 — Additional Photos 12



Photo 28 — Additional Photos 25



Photo 29 — Additional Photos 26



Photo 30 — Additional Photos 27



Photo 31 — Additional Photos 28



Photo 32 — Additional Photos 29



Photo 33 — Additional Photos 30



Photo 34 — Additional Photos 31



Photo 35 — Additional Photos 32



Photo 36 — Additional Photos 33



Photo 37 — Additional Photos 34



Photo 38 — Additional Photos 35



Photo 39 — Additional Photos 36



Photo 40 — Additional Photos 37



Photo 41 — Additional Photos 38



Photo 42 — Additional Photos 39



Photo 43 — Additional Photos 40



Photo 44 — Additional Photos 41



Photo 45 — Additional Photos 42



Photo 46 — Additional Photos 43



Photo 47 — Additional Photos 44



Photo 48 — Additional Photos 45



Photo 49 — Additional Photos 46



Photo 50 — Additional Photos 47




Photo 51 — Additional Photos 48



Photo 52 — Additional Photos 49



Photo 53 — Additional Photos 50



Photo 54 — Additional Photos 51



Photo 55 — Additional Photos 52



Photo 56 — Additional Photos 53



Photo 57 — Additional Photos 54

