

Site HOTO Report — SYL_X0233

Project Tiger · Dhaly Infratech → Alliance Computers Limited · Generated 10-Sep-2026 22:58 BD time

55%

FORM COMPLETION

0/0

CHECKLIST OK

2

OPEN SNAGS

2

TOTAL SNAGS

43

PHOTOS ATTACHED

Incomplete: the following expected fields were left blank in this submission — Site Type, BTS Type, Site Sharing, Site Photo, Fuel Gauge Photo.

SITE & HANDOVER DETAILS

SITE CODE	SYL_X0233	ZONE	Sylhet
HOTO DATE	2026-09-05	DISTRICT	Sylhet
HANDOVER ORG	—	TAKEOVER ORG	—
HANDOVER PERSON	Ali Bahar	TAKEOVER PERSON	Md. Hemayetul Islam
HANDOVER PHONE	01778700969	TAKEOVER PHONE	01847426873
INSPECTED BY	Ali Bahar	SECURITY GUARD	—
ACCESS KEY HANDED OVER	—	SITE TYPE	Not Filled
BTS TYPE	Not Filled		
SHARED WITH OPERATOR	Not Filled	SHARED OPERATOR NAME	—

GENERATOR INFORMATION

DG BRAND	Pramac	GENSET ASSET NO.	—
CAPACITY (KVA)	30	TYPE	—
FUEL TANK CAPACITY	2000	PRESENT RH	3732.42
FUEL (NO WATER)	— L	FUEL (TOTAL)	254 L
WATER AMOUNT	— L	FUEL AMOUNT (WORD)	—
DG SITE TYPE	—	DG LOCKED AFTER FUELING	—
DG PRESENT STATUS	OK	GENSET ON ALARM	—
BATTERY BRAND	Hamko	BATTERY SERIAL	H2466190705
BATTERY AH	100	ENGINE SERIAL	—
ATS BRAND	—	ATS MODE	—
RH METER TYPE	Manual meter	LAST SERVICE DATE	2026-05-14
KEY TYPE	—	KEY STATUS — BTS	—
KEY STATUS — DG ROOM	—		

ACTIVE DG	—	CONNECTED FUEL TANKS	—
FAULTY/DISCONNECTED DG	—	FAULTY/DISCONNECTED TANKS	—






SNAGS FOUND (2)

SNAG #	SYSTEM	CATEGORY	COMPONENT	STATUS	OBSERVATIONS	ACTION	PHOTO
S-119	General	—	(from HOTO Telegram group photo -- needs review)	Faulty	Auto-tagged as Snag from imported chat photo; please fill in the actual system/category/observation.	Open	
S-120	General	—	(from HOTO Telegram group photo -- needs review)	Faulty	Auto-tagged as Snag from imported chat photo; please fill in the actual system/category/observation.	Open	

DEFICIENCIES & SAFETY REMARKS

DG MAJOR DEFICIENCIES	DG Radiator need to servicing; DG Battery water low level; DG Room need to clean; DG Room Top tin need change; DG fuel tank lock - broken (from paper handover checklist).
SAFETY REMARKS	—
GENERAL REMARKS	Technical fields backfilled from a paper handover checklist photo that was misfiled under SYL_X0017's Extra photos (SYL_X0017_EXTRA_043.jpg) -- the document's own printed Site ID field reads SYL-X0233. Photo has been relocated to this visit. Backfilled 2026-09-09.

SITE PHOTOS

 Not Filled Site / Nameplate	 DG RH / Meter	 Not Filled Fuel Gauge				
 Handover Checklist Document	 Additional	 Additional	 Additional	 Additional	 Additional	 Additional

Ali Bahar

Handed Over By · —
01778700969

Date: _____

Md. Hemayetul Islam

Taken Over By · —
01847426873

Date: _____

BL Concern · Name / Signature

Date: _____

APPENDIX — PHOTO EVIDENCE (43)

Full-size reference photos for SYL_X0233, grouped by type and numbered for cross-reference against the tables above.

REQUIRED SITE PHOTOS (1)



Photo 1 — DG RH / Meter

SNAG EVIDENCE PHOTOS (2)




Photo 2 — S-119 — (from HOTO Telegram group photo
-- needs review)




Photo 3 — S-120 — (from HOTO Telegram group photo
-- needs review)

HANDOVER CHECKLIST DOCUMENT (1)

Handover Checklist Document for SYL_X0233. The document is a form with various fields for project details, equipment, and inspection points. It includes handwritten notes and signatures.

SYL_X0233 - Project Tiger HOTO
Additional Site Photo
09-Sep-2026 14:24 BD time

Photo 4 — Handover Checklist Document 1

ADDITIONAL PHOTOS (39)



Photo 5 — Additional Photos 1



Photo 6 — Additional Photos 2




Photo 7 — Additional Photos 3




Photo 8 — Additional Photos 4



Photo 9 — Additional Photos 5



Photo 10 — Additional Photos 6



Photo 11 — Additional Photos 7




Photo 12 — Additional Photos 8




Photo 13 — Additional Photos 9




Photo 14 — Additional Photos 10



Photo 15 — Additional Photos 11



Photo 16 — Additional Photos 12



Photo 17 — Additional Photos 13



Photo 18 — Additional Photos 14



Photo 19 — Additional Photos 15



Photo 20 — Additional Photos 16



Photo 21 — Additional Photos 17



Photo 22 — Additional Photos 18



Photo 23 — Additional Photos 19



Photo 24 — Additional Photos 20



Photo 25 — Additional Photos 21



Photo 26 — Additional Photos 22



Photo 27 — Additional Photos 23



Photo 28 — Additional Photos 24




Photo 29 — Additional Photos 25



Photo 30 — Additional Photos 26



Photo 31 — Additional Photos 27



Photo 32 — Additional Photos 28



Photo 33 — Additional Photos 29



Photo 34 — Additional Photos 30



Photo 35 — Additional Photos 31



Photo 36 — Additional Photos 32



Photo 37 — Additional Photos 33



Photo 38 — Additional Photos 34



Photo 39 — Additional Photos 35



Photo 40 — Additional Photos 36



Photo 41 — Additional Photos 37



Photo 42 — Additional Photos 38




Photo 43 — Additional Photos 39